

N848AG Serial 401



N848AG HIGHLIGHTS





Low Time Engines on MSP Delivered w/ Fresh MPI's APU on MSP Certified 135 **Gross Weight Mod** Always U.S. Owned

All Specifications are subject to verification upon inspection.

N848AG TIMES & CYCLES



Airframe Total Time: 3519

Landings: 2551

Engines TFE731-20BR-1B

Engine 1: 3519 hrs 2551 cycles

Engine 2: 3519 hrs 2551 cycles

APU Honeywell RE100 1542 hrs

3224 cycles

All Specifications are subject to verification upon inspection.



N848AG AVIONICS



Honeywell Primus 1000

(4) Honeywell DU-870 Electronic Flight Instrument System

Integrated Honeywell Primus 1000 Autopilot

Dual Honeywell RM-855 Radio Management Units

Dual Universal UNS-1Ew FMS

Dual Honeywell RNZ-851 Nav Units (VOR/ILS, DME)

Dual Honeywell RCZ-833K Comm Units

Dual Honeywell LCR-100 AHRS

Honeywell TCAS II
Honeywell Mark V EGPWS
Honeywell WU-660 Weather Radar
Honeywell RT-300 Radio Altimeter
Aerosonic Standby Altimeter
Honeywell CVR (30 Minutes)
Artex C406-2 ELT



N848AG INTERIOR



Floor plan 3A features a standard double club configuration with forward galley, crew closet, aft lavatory and vanity. Cabin seats are Balsa royal hide leather with Walnut color seat base accent trim, headliner and cabin sidewalls are Almond ultraleather. Cabinetry is a natural color Sapele Ponmele wood veneer with high gloss finish. Plating is in Light Coffee Bronze with satin finish.









N848AG EXTERIOR



Overall Matterhorn White with Bright Poppy Orange and Bristol Blue trim.






N848AG ADDITIONAL EQUIPMENT



Electronic Flight Bag w/XM Graphical Weather Tail Illumination Package **Pulsating Recognition Lights** Cabin Audio / Video / DVD System Forward and Aft LCD Video Monitors Airshow 410 **XM Radio Concord 38 Amp Hour Batteries Exterior Lighting Package Under Seat Storage Drawers** Lavatory Flip-Down Baggage Shelf **Galley Rest Seat** 110v Cabin Outlet





OLDS AIRCRAFT SALES & CONSULTING, LLC

CONTACT:
Brian Olds
616-437-7712
Brian@oldsaircraft.com

All Specifications are subject to verification upon inspection.